

# Firmware Release Notes

## Araknis Wireless Access Points

Version 2.0.02



### Release Details

Release Date	11/21/2020
Firmware Version	2.0.02
Product SKUs Affected	AN-510-AP-I-AC AN-810-AP-I-AC

**IMPORTANT: Reboot your AP *prior* to applying this firmware.**

**NOTE: Clear browser cache & settings prior to and after the firmware upgrade.**

### Added/Removed Features

- Updated user accounts / user access to accommodate password law constraints set by California's IoT security legislation.

### Resolved Cloud Issues

- Implemented long-term improvement for persistent OvrC connectivity.
- Enabling/Disabling DST from OvrC now works properly, even if you adjust it multiple times.

### Resolved Functional/Local Issues

- Improved functionality for environments that experience periodic loss of internet and/or device connectivity.
- Fixed issue where transmit power was not properly designated as 5GHz and 2.4GHz on the advanced wireless settings page.
- Fixed issue with the 510/810 wherein the help bubble for advanced wireless settings "transmit power" help did not display the correct values.
- Fixed issue wherein pages with large tables and graphics have a double scroll which slowed navigation within the interface